SKILLING, HELLE, CHRISTIANSEN, ROBERTSON — Structural & Civil Engineers

PROJECT THE WORLD TRADE CENTER | TITLE EXTERIOR WALL-DAMPER CONN. REPAIR-FL 7&9 | DATE 8/20/69

REVISIONS



NOTES:
1. Bolt holes may be reamed to accomodate mis-matched holes providing that edge distances are maintained as shown in Detail 1 ℄2.
2. Were edge distances cannot be maintained Contractor may rectify the deficiency by plug welding and by re-reaming.



Max. reaming of slots Detail 1



Max. reaming of holes Detail 2
Provide thickened washers per specs.

R

DESIGNED H. Root.
DRAWN A. FRANQUI
REVIEWED

19-AB-958